


132 Saltley Road Saltley Birmingham

B7 4TH





Certificate No. 5133 Order No.

This is to certify that we have carried out an in-house test on a sample of the supplied fabric detailed above.

The results from the test show a satisfactory PASS to BS 5867 ; Part 2 : (Tested according to EN-ISO 15025: 2002 Face Ignition).

No tests have been carried out on the durability of the fabric's flame retardant properties, and we are therefore unable to provide any recommendations regarding fabric care.

Yours faithfully

For J E Talbot B Sc (Head of Testing) GS/F/12



KBTLtd

132 Saltley Road

Saltley

Birmingham

B7 4TH

Date

Fabric



02/02/11

Red Hessian

Length 0.25 metres Certificate No. 5133

Order No.

This is to certify that we have carried out an in-house test on a sample of the supplied fabric detailed above

The results from the test show a satisfactiory PASS to BS 476 . Part 7 : 1987: Class 1 when used in conjunction with a suitable substrate

No further tests have been carried out on the durability of the fabric's flame retardant properties and we are therefore unable to provide any recommendation regarding fabric care.

Yours faithfully

For J E Talbot B Sc (Head of Testing)



K B T Ltd 132 Saltley Road Saltley Birmingham

B7 4TH



Certificate No. 5133 Order No.

Date 02/02/11
Fabric Red Hessian
Length 0.25 metres

Ref. 'The Furniture and Furnishings (Fire) (Safety) Regulations 1988."

This is to certify that we have tested a sample of the above supplied fabric to

a) BS 5852 Part 1: 1979, Ignition Source 0 (Cigarette)

b) BS 5852 part 1 1979, Ignition Source 1 (Match)

each following the water-soaking procedure set out in clauses 4.2 to 4.5 of BS 5651 : 1978.

Tests were carried out in conjunction with a non flame-retardant polyurethane foam corresponding to the specification set out in BS 3379 type B, hardness grade 130 and of a density of 20-22 kg per m³.

The results from our in-house test were a satisfactory PASS.

No further tests have been carried out on the durability of the fabric's flame retardant properties, and we are therefore unable to provide any recommendation regarding fabric care.

Yours faithfully

For J E Talbot B.Sc (Head of Testing) GS/F/12



K B T Ltd

132 Saltley Road

Saltley

Birmingham

B7 4TH

Date

Fabric

Length



02/02/11 Certificate No. 5133
Red Hessian Order No. 0.25 metres

This is to certify that we have carried out an in-house test on a sample of the supplied fabric detailed above.

The results from the test show a PASS to pass BS 5852 2006, Ignition Source 5.

No further tests have been carried out on the durability of the fabric's flame retardant properties, and we are therefore unable to provide any recommendation regarding fabric care.

Yours faithfully

For J E Talbot B.Sc (Head of Testing) GS/F/12

